

Oil Field Environmental Incident Summary

Incident: 20150216111806 **Date/Time of Notice:** 02/16/2015 11:18

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: GEVING 1-09H

Field Name: PARSHALL

Well File #: 16467

Date Incident: 2/15/2015 **Time Incident:** 13:08

Facility ID Number:

County: MOUNTRAIL

Twp: 152

Rng: 90

Sec: 9

Qtr:

Location Description:

Submitted By: Danielle Dupay

Received By:

Contact Person: Danielle Dupay
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	1.5	Barrels	1.5	Barrels	1.5	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 10/30/2015

Clean Up Concluded: 2/16/2015

Risk Evaluation:

N/A

Areal Extent:

N/A

Potential Environmental Impacts:

None

Action Taken or Planned:

Liquids were removed from and when the repairs are made the affected material will be removed.

Wastes Disposal Location: Liquids went to SWD and Solids TBD.

Agencies Involved: TAT and MHA

Updates

Date: 2/16/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to unspecified cause, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.